

County	Manufacturer	Make And Model	Serial	Firmware Ver	Firmware EAC	Firmware EAC Date	Firmware CDOS Certification Number	CDOS Date	Hardware Ver	Hardware EAC	Hardware EAC Date	Hardware CDOS Certification Number	CDOS Date	Software Version	Software EAC	Software EAC Date	Software CDOS Certification Number	CDOS Date
Weld	Diebold	Accuvote TSx	269044	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	272557	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	272592	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	272594	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	273607	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	284637	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	263710	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	284602	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	263722	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	263718	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	268574	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	277843	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	263711	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	284649	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Weld	Diebold	Accuvote TSx	284607	4.6.4	N-1-06-12-22-002 (2002)	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	TSx w/ V-VPAT	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006	GEMS 1.18.24	N-1-06-12-22-002	10/3/2005	2005-CDOS-DIE-001-1123	3/3/2006
Yuma	HART	DRE/Touch Screen	A0AF53	4.0.19	N-1-04-22-22-004 (2002)	3/6/2006	2006-CDOS-HAR-001-0109	6/9/2006	eSlate3000	N-1-04-22-22-002	3/6/2006	2006-CDOS-HAR-001-0109	6/9/2006	BOSS 4.2.13	N-1-04-22-22-004	3/6/2006	2006-CDOS-HAR-001-0109	6/9/2006
Yuma	HART	Precinct Scanner	G78682	1.1.6	N-1-04-22-22-002 (2002)	5/18/2005	2006-CDOS-HAR-001-0109	6/9/2006	eScan	N-1-04-22-22-002	5/18/2005	2006-CDOS-HAR-001-0109	6/9/2006	BOSS 4.2.13	N-1-04-22-22-004	3/6/2006	2006-CDOS-HAR-001-0109	6/9/2006
Yuma	HART	DRE/Touch Screen	A0B054	4.0.19	N-1-04-22-22-004 (2002)	3/6/2006	2006-CDOS-HAR-001-0109	6/9/2006	eSlate3000	N-1-04-22-22-002	3/6/2006	2006-CDOS-HAR-001-0109	6/9/2006	BOSS 4.2.13	N-1-04-22-22-004	3/6/2006	2006-CDOS-HAR-001-0109	6/9/2006
Yuma	HART	Precinct Scanner	G786D6	1.1.6	N-1-04-22-22-002 (2002)	5/18/2005	2006-CDOS-HAR-001-0109	6/9/2006	eScan	N-1-04-22-22-002	5/18/2005	2006-CDOS-HAR-001-0109	6/9/2006	BOSS 4.2.13	N-1-04-22-22-004	3/6/2006	2006-CDOS-HAR-001-0109	6/9/2006